

Work Order ID 101385***101385***

Page 1

Wednesday, May 08, 2013 3:49:06 PM

Item ID: D3552-11 Accept *N900040100* Setup Start *NS1*
Revision ID: Stop *NS2*
Item Name: Door Prop
Start Date: 5/8/2013 Start Qty: 3.00 *3* Cust Item ID:
Required Date: 5/8/2013 Req'd Qty: 3.00 *3* Customer:
Reference: RA111507 - RETURN

Approvals: Process Plan: MF Date: 3-1 Tooling: Date: Run Start *NR1*
QC: Date: SPC (Y/N): Date: Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3552	K								

150

0.00

150

QC

Quality Control

Memo

INSPECT RA 111507
D3552-11 X 3 B#94728PARTS ARE ACTUALLY D3552-9
AND HAVE NO BATCH NUMBER

UNABLE TO FIND OUT WHAT BATCH PARTS ARE

SCRAP

0.00

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Quality Control

Memo

0.00

DAS
16
9-89 13/04/10

(15)

13/5/10 JJ

13-05-9

Picklist Print

Wednesday, May 08, 2013 3:49:06 PM

Page 1

Work Order ID: 101385

Parent Item: D3552-11

Parent Item Name: Door Prop

Start Date: 5/8/2013

Required Date: 5/8/2013

Start Qty: 3.00

Required Qty: 3.00

Comments: IPP Rev:B 09-04-20 rev.d as per dwg DD verified by:EC IPP Rev:C as per dwg RevE DD
10.02.17 verified by:EC IPP Rev:D 10.12.03 as per dwg rev.G DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3552-11 Door Prop		Manufactured	No				Each	10.0000		3			

Location

Loc Qty

Loc Code

FG

4

80345

2

96447

2

ST260

6

98442

6

3x 94728 h

RA 111507 D3552-11

Received @ Dart March 26th, 2013
Inspected @ Dart April 10th, 2013

Customer: MUSTANG HELICOPTERS
Customer Contact: BRET KRAUSS
Shipped from: BLACKFALDS AB, CANADA

Instructions for RA 111507 D3552-11

- Parts are actually D3552-9
- Parts cannot be returned to stock do not have a BATCH # on them
- Unable to know exactly what BATCH parts are

Scrap D3552-9

Time Estimate = 1 HOUR
Departments Required: Quality Control
Pictures Attached = NO
QTY INSPECTED = x1 D3552-9

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**